

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / TECH/ WF.21-Oct-2022 / 108 / 2022-23.

dated: 24/01/2023

Name of the Work: Construction of retaining wall near St.Cruz chapel Colmorod in Margao Constituency.

Sample Sent by: Assistant Engineer, SD III, WD III, WRD, Gogol- Margao-Goa

Letter No: NO. 306/SD III/ WD III/ WRD/ 2022-23/429.

Dated:- 13-01-2023

Received on: 16-01-2023

Date of Testing 18-01-2023

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F. 21/05/2022	Metal Sand	FM Silt & Clay Grading	3.004 1.80% Zone II	2.3 to 3.1 Upto 5% Zone I to III	

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD III, WD III , WRD, Gogol- Margao-Goa.
- 2) The Executive Engineer, Works Division III, WRD,Ponda- Goa.
- 3) Executive Engineer, WD XI, WRD,Rawanfong-Goa.
- 4) The Surveyor of Works,Quality Control, C.P.O.,Water Resources Dept., Sinchai Bhavan,Alto Porvorim-Goa.
- 5) Office File