

NO.WRD/WDXI/SDIII/TECH/W.F.150/2021/2022-23/ 27.

Dated:- 03-11-2022.

GOVERNMENT OF GOA
SD III (QC) , WRD, GOGAL, MARGAO- GOA.

NAME OF THE WORK: Providing urgent protective measures to the collapsed portion near the bandhara piers of Sarzora tank at Sarzora in Salcete Taluka.

SAMPLE SENT BY: AE, SD V, WD XII, WRD, Quepem- Goa.

NAME OF THE AGENCY

TESTING PERIOD

07 days.

REPORT NO	SAMPLE NOS.	CASTING DATE	TESTING DATE	LOCATION OF SAMPLE	MIX PROPOTION	REQUIRED STRENGTH	Comp sth in Kg/cm2	Avg. Comp Kg/cm2	LETTER No / DATED
1	F.149/15/2021						142.22		No. WRD/WD XII/SD V/
	F.149/16/2021	27-09-2022	4/10/2022	Foundation	1.2.4	140 kg/cm2	146.67	145.19	F.15/144/2022-23.
	F.149/17/2021						146.67		DATED: 04-10-2022.
2	F.149/18/2021						146.67		
	F.149/19/2021	28-09-2022	4/10/2022	Foundation	1.2.4	140 kg/cm2	142.22	143.70	do
	F.149/20/2021						142.22		
3	F.149/21/2021						142.22		
	F.149/22/2021	29-09-2022	6/10/2022	Superstructure	1.2.4	140 kg/cm2	142.22	145.18	do
	F.149/23/2021						151.11		

JUNIOR ENGINEER.

ASSISTANT ENGINEER