

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / TECH / WF.10-Oct-2022 / 29 /2022-23.

Dated: **07-11-2022**

Name of the Work: Improvement of sluice gate (2 nos) and upgradation of inspection path of Deussua tank in Village Deussua in Velim Constituency.

Sample Sent by: Assistant Engineer , SD I , WD II , WRD , Rawanfond- Goa.

Letter No: WRD / SD I/WD II/F. Estt/458/2022-23.

Dated:- 01-11-2022.

Received on: 1/11/2022

Date of Testing 4/11/2022

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F.10/01/2022	Coarse Sand	FM Silt & Clay Grading	2.946 2.00% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
F.10/02/2022	Aggregate-20 mm	Grading		As per IS-383:2016	To get the 20mm graded aggregate nominal size blend
F.10/03/2022	Aggregate- 10 mm	Grading		As per IS-383:2016	20mm & 10 mm metal in 1:1 proportion.

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD I, WD II , WRD Rawanfond- Goa.
- 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
- 3) The Executive Engineer, Works Division II, WRD, Rawanfond- Goa.
- 4) Office File.