

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / TECH / WF. 13-Oct-2022 /32 /2022-23.

Dated:14/11/2022

Name of the Work: Construction of Open Type Bandhara near Vodli Handi and Improvement of nallah and Dakti Handi in Sy.No. 96/8, 97/19 in V.P. Nagoa in Nuvem Constituency.

Sample Sent by: Assistant Engineer, SD I, WD II, WRD, Rawanfond -Goa

Letter No: No. WRD/SD I/ WD II/ F.Estt/487/2022-23.

Dated:- 11/11/2022

Received on: 11/11/2022

Date of Testing: 11-11-2022

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F. 13/01/2022	Coarse Sand	FM Silt & Clay Grading	2.606 1.40% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
F.13/02/2022	Aggregate-20 mm	Grading		As per IS-383:2016	To get the 20mm graded aggregate nominal size blend 20mm & 10 mm metal in 1:1 proportion.
F.13/03/2022	Aggregate- 10 mm	Grading		As per IS-383:2016	

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD I, WD II, WRD, Rawanfond-Goa.
- 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
- 3) Executive Engineer, WD II, WRD, Rawanfond-Goa.
- 4) Office File.