

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / TECH/ WF.21-Oct-2022 /50 / 2022-23.

dated: 02/12/2022

Name of the Work: Construction of retaining wall near St.Cruz chapel Colmorod in Margao Constituency.

Sample Sent by: Assistant Engineer, SD III, WD III, WRD, Gogol- Margao-Goa

Letter No: NO. 306/SD III/ WD III/ WRD/ 2022-23/330.

Dated:- 14-11-2022

Received on: 30-11-2022

Date of Testing 2/12/2022

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F. 21/01/2022	Coarse Sand	FM Silt & Clay Grading	2.368 2.00% Zone III	2.3 to 3.1 Upto 5% Zone I to III	
F. 21/02/2022	Aggregate-20 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	To get the 20mm graded aggregate nominal size blend 20mm & 10 mm metal in 1:1 proportion.
F. 21/03/2022	Aggregate- 10 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD III, WD III, WRD, Gogol- Margao-Goa.
- 2) The Executive Engineer, Works Division III, WRD, Ponda- Goa.
- 3) Executive Engineer, WD XI, WRD, Rawanfond-Goa.
- 4) Office File.