

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59 / WF.98/ / 2021-22. dated:

Name of the Work: Urgent Protection to nallah bank in Sy.No. 83 at Daab Karsange in V.P. Borim of Shiroda
Constituency Taluka Ponda.

Sample Sent by :- Assistant Engineer, SD IV, WD XI, WRD, Ponda - Goa.

Letter no:- No. WRD/WD XI/SD IV/W.F.cf/256/2021-22.

Dated:- 20-08-2021

Received on: 20-08-2021

Date of Testing: 23-08-2021

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
535/2021	Coarse Sand	FM Silt & Clay Grading	2.610 1.60% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
536/2021	Aggregate-20 mm	Grading		As per IS-383:2016	To get the 20mm graded aggregate nominal size blend 20mm & 10 mm metal in 1:1 proportion.
537/2021	Aggregate- 10 mm	Grading		As per IS-383:2016	

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD IV, WD XI, WRD, Ponda-Goa.
- 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
- 3) Office File.
- 4) Office File.