

GOVERNMENT OF GOA  
**WATER RESOURCES DEPARTMENT**  
 S.D.III, WORK DIVISION XI, QUALITY CONTROL  
 GOGAL, MARGAO- GOA

<b>NO:</b> WRD / WD XI / SD III/ F.59 / W.F. 44/2020-21 / <b>230</b> / 2020-21		Dated: 04-03-2021	
<b>Name of the Work :-</b> Improvement to Ganapatiwada Talli in ward No. 05 of V.P. Betqui Candola oin Priol Constituency.			
<b>REQUISITION DETAILS:</b> NO: WRD / WD XI / SD IV/ F. cf / 161/ 2020-21. Dated:-01-03-2021			
<b>SAMPLE SENT BY:</b> Assistant Engineer, Sub. Div. IV, Works Div. XI, WRD, Ponda- Goa.			
<b>SAMPLE RECEIVED ON:</b> 2/3/2021			
<b>TYPE OF SAMPLE:</b> Latrite boulders			
<b>STRENGTH REQUIRED:</b>			
<b>TESTING DATE:</b> 04-03-2021			
<b>TESTED BY:</b> Junior Engineer		<b>AUTHORISED BY:</b> AE, SD III, QC.	
<b>AGENCY NAME:</b>			
Sr. No:	SAMPLE NUMBER	Comp. strength in Kg/sq.cm.	AVERAGE Kg/sq.cm
1	219	37.50	<b>39.33</b>
2	220	40.00	
3	221	41.67	
4	222	40.00	
5	223	37.50	

Junior Engineer

Assistant Engineer

To,  
 Assistant Engineer, Sub- Div. IV, Works Div. XI, WRD, Ponda- Goa.

Copy Submitted To:

1. Executive Engineer, Works Div. XI, WRD, Rawanfond-Goa .
2. Office File No: F-59