

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59. W.F. 02/2020 /152 / 2020-21

dated: 30/10/2020

Name of the Work: Re- Construction of Retaining Wall of nallah at Rawanfond near Caeiro Residential Building in V.P.
Aquem - Baixo, Salcete- Goa.

Sample Sent by :- Assistant Engineer, SD I, WD II , WRD, Rawanfond- Goa.

Letter no:- No. WRD/ SD I/WD II/ F.Esst/57232020-21.

Dated:- 21-10-2020

Received On: 21-10-2020

Date of Tesing: 30-10-2020

REPORT

Sr No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
06/20	Coarse Sand	FM Silt & Clay Grading	2.684 2.60% Zone- II	2.3 to 3.1 Upto 5% I to III Zone	
07/20	Aggregate-20 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	To get the 20mm graded aggregate nominal size blend 20mm & 10 mm metal in 1:1 proportion.
08/20	Aggregate- 10 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SDI, WD II, WRD, Rawanfond, Goa.
- 2) The Executive Engineer, Works Division II, WRD, Rawanfond, Goa.
- 3) Executive Engineer, WD XI, WRD, Rawanfond -Goa.
- 4) Office File.

