

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59 / WF.86/2021/ 32 / 2021-22. dated: 17/05/2021

Name of the Work: Improvement to Gabru Pond in Sy.No. 185/2 at Daugem ward of Nuvem Village Panchayat in Nuvem Constituency.

Sample Sent by: Assistant Engineer, SD I, WD II, WRD, Aquem-Baixo,Rawandfond,Salcete-Goa

Letter No: WRD / SD I / WD II / F.Esst / 96/ 2021-22.

Dated:- 12/5/2021

Received on: 17-05-2021

Date of Testing: 17-05-2021

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
458/2021	Coarse Sand	FM Silt & Clay Grading	2.686 1.60% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
459/2021	Aggregate-20 mm	Grading		As per IS-383:2016	To get the 20mm graded aggregate nominal size blend 20mm & 10 mm metal in 1:1 proportion.
460/2021	Aggregate- 10 mm	Grading		As per IS-383:2016	

Junior Engineer

Assistant Engineer

- Copy submitted to
- 1) Assistant Engineer, SD I, WD II, WRD, Aquem-Baixo, Rawandfond, Salcete-Goa.
 - 2) The Executive Engineer, Works Division XI, WRD, Rawandfond- Goa.
 - 3) Executive Engineer, WD II, WRD, Aquem-Baixo, Rawandfond, Salcete-Goa.
 - 4) Office File.