

**GOVERNMENT OF GOA**  
**WATER RESOURCES DEPARTMENT**  
**S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY**  
**Gogol - Margao - Goa.**

No. WRD / WD XI / SDIII / F.59 / WF. 93/2021/ 56 / 2021-22.

dated: 18/06/2021

Name of the Work: Protection wall for nallah in Sy.No. 26 in Village Dramapur in Velim Constituency.

Sample Sent by: Assistant Engineer, SD I, WD II, WRD, Aquem-Baixo, Rawandfond, Salcete-Goa

Letter No: WRD / SD I / WD II / F.Esst / 150/ 2021-22.

Dated:- 10/6/2021

Received on: 16-06-2021

Date of Testing: 18-06-2021

**REPORT**

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
505/2021	Coarse Sand	FM Silt & Clay Grading	2.894 2.20% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
506/2021	Aggregate-20 mm	Grading		As per IS-383:2016	To get the 20mm graded aggregate nominal size blend 20mm & 10 mm metal in 1:1 proportion.
507/2021	Aggregate- 10 mm	Grading		As per IS-383:2016	

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD I, WD II, WRD, Aquem-Baixo, Rawandfond, Salcete-Goa.
- 2) The Executive Engineer, Works Division XI, WRD, Rawandfond- Goa.
- 3) Executive Engineer, WD II, WRD, Aquem-Baixo, Rawandfond, Salcete-Goa.
- 4) Office File.