

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59. W.F. 75/2021 / 22 / 2021-22

dated:05/05/21

Name of the Work: Development of Gonsua lake in Sy. No. 14/21 at Village gonsua in V.P. Batelbatim in Nuvem Constituency of Salcete taluka

Sample Sent by :- Assistant Engineer, SD I, WD II , WRD, Rawanfond- Goa.

Letter no:- No. WRD/SD I/WD II/F.Estt/50/2021-22.

Dated:- 20-04-2021

Received On: 03-05-2021

Date of Tesing: 05/05/2021

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
398/2021	Coarse Sand	FM Silt & Clay Grading	2.874 2.50% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
399/2021	Metal Sand	FM Silt & Clay Grading	3.096 4.80% Zone I	2.3 to 3.1 Upto 5% I to III Zone	
400/2021	Aggregate-20 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	To get the 40mm graded aggregate nominal size blend 40mm,20mm & 10 mm metal in 1:1:1 proportion.
401/2021	Aggregate- 10 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD I, WD II , WRD, Rawanfond- Goa.
- 2) Executive Engineer, WD XI, WRD, Rawanfond -Goa.
- 3) Office File.