

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59. W.F. 81/2021 / 29 / 2021-22

dated:07/05/21

Name of the Work: Improvement to nallah at Konem Priol in Priol Constituency

Sample Sent by :- Assistant Engineer, SD IV, WD XI, WRD, Ponda - Goa.

Letter no:- No. WRD/WD XI/SD IV/F.CF/57/2021-22.

Dated:- 04-05-2021

Received On: 04/05/2021

Date of Tesing: 07/05/2021

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
427/2021	Coarse Sand	FM Silt & Clay Grading	2.618 1.60% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
428/2021	Metal Sand	FM Silt & Clay Grading	3.032 1.80% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
429/2021	Aggregate-20 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	To get the 40mm graded aggregate nominal size blend
430/2021	Aggregate- 12.50 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	40mm,20mm & 10 mm metal in 1:1:1 proportion.

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD IV, WD XI, WRD, Ponda - Goa.
- 2) Executive Engineer, WD XI, WRD, Rawanfond -Goa.
- 3) Office File.