

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59 / WF.80 / 27 / 2021-22. dated: 06/05/21

Name of the Work: Construction of protection wall to the nallah side bank in Sy. No. 59/1 in village Nagoa in Nuvem Constituency of Salcete taluka

Sample Sent by: Assistant Engineer, SD I, WD II, WRD, Aquem-Baixo, Rawandfond, Salcete-Goa

Letter No: WRD / SD I / WD II / F.Esst / 97/ 2021-22.

Dated:- 30-04-2021

Received on: 3/5/2021

Date of Testing: 06-05-2021

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
389/21	Coarse Sand	FM Silt & Clay Grading	2.894 2.20% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
390/21	Aggregate-20 mm	Grading		As per IS-383:2016	To get the 20mm graded aggregate nominal size blend
391/21	Aggregate- 10 mm	Grading		As per IS-383:2016	20mm & 10 mm metal in 1:1 proportion.

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD I, WD II, WRD, Aquem-Baixo, Rawandfond, Salcete-Goa.
- 2) The Executive Engineer, Works Division XI, WRD, Rawandfond- Goa.
- 3) Executive Engineer, WD II, WRD, Aquem-Baixo, Rawandfond, Salcete-Goa.
- 4) Office File.