

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59./ W.F. 53/2020-21/ 192 / 2021-22. dated: 03/01/2022

Name of the Work: Improvement and covering of developed nallah's at various location in Margao Constituency.

Sample Sent by :- Assistant Engineer, SD III, WD III, WRD, Gogol- Margao- Goa.

letter no:- No.246/SD III/WD III/WRD/2021-22/350.

Dated:- 30-11-2021

Received On: 17-12-2021

Date of Testing: 20-12-2021

REPORT

| Sample No. | Type of Sample | Tested for | Result | Permissible value | REMARKS |
|------------|------------------|------------------------------|---------------------------|---|---|
| 264/2021 | Coarse sand | FM Silt & Clay Grading | 2.606 1.40% Zone II | 2.3 to 3.1 Upto 5% I to III Zone | |
| 265/2021 | Aggregate-20 mm | Grading | | As per IS-383-1970 (Re-affirmed in 1990) | To get the 20mm graded aggregate nominal size blend 20mm & 10 mm metal in 1:1 proportion. |
| 266/2021 | Aggregate- 10 mm | Grading | | As per IS-383-1970 (Re-affirmed in 1990) | |

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD III, WD III, WRD, Gogol- Margao-Goa.
- 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
- 3) Executive Engineer, WD III, WRD, Ponda-Goa.
- 4) Office File.