

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59 / WF.65/2020-21 / 04 / 2021-22. dated: 08/04/2021

Name of the Work: Protection wall for nallah in Sy. No. 318, 322 and for pond in Sy. No. 63 in Village Velim Constituency.

Sample Sent by: Assistant Engineer, SD I, WD II, WRD, Rawanfond -Goa

Letter No: No. WRD/SD I/ WD II/ F.Estt/956/2020-21

Dated:- 30-03-2021

Received on: 5/4/2021

Date of Testing: 08-04-2021

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
323/2021	Coarse Sand	FM Silt & Clay Grading	2.509 1.40% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
324/2021	Aggregate-20 mm	Grading		As per IS-383:2016	To get the 20mm graded aggregate nominal size blend 20mm & 10 mm metal in 1:1 proportion.
325/2021	Aggregate- 10 mm	Grading		As per IS-383:2016	

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD I, WD II, WRD, Rawanfond-Goa.
- 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
- 3) Executive Engineer, WD II, WRD, Rawanfond-Goa.
- 4) Office File.