

**GOVERNMENT OF GOA**  
**WATER RESOURCES DEPARTMENT**  
**S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY**  
**Gogol - Margao - Goa.**

No. WRD / WD XI / SDIII / F.59. W.F. 06/2021 / 124 / 2021-22.

dated:03/11/2021

Name of the Work: Construction of Slab culvert for road access to the fields under Sy.No. 397/9, 397/6 and 397/8 of Chinchinim Village of Salcete Taluka for the year 2021-22.

Sample Sent by :- Assistant Engineer, SD III, WD XIV , WRD, Cuncolim- Goa.

Letter no:- No. WRD/ SD III/WD XIV/ W.F. 1/2021-22/151.

Dated:- 29-10-2021

Received On: 01-11-2021

Date of Testing: 03-11-2021

**REPORT**

Sr No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F.6/1/2021	Coarse Sand	FM Silt & Clay Grading	2.568 3.00% Zone- II	2.3 to 3.1 Upto 5% I to III Zone	
F.6/2/2021	Aggregate-20 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	To get the 20mm graded aggregate nominal size blend
F.6/3/2021	Aggregate- 10 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	20mm & 10 mm metal in 1:1 proportion.

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD III, WD XIV, WRD, Cuncolim- Goa.
- 2) The Executive Engineer, Works Division XIV, WRD, Rawanfond, Goa.
- 3) Executive Engineer, WD XI, WRD, Rawanfond -Goa.
- 4) Office File.