

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59 / WF.15/2021 / 138 / 2021-22.

dated: 18/11/2021

Name of the Work: Stabilization of bank of nallah from Anthony Fernandes to Digamber Padwal house at Deulmol, Shirvoi in Quepem Constituency.

Sample Sent by :- Assistant Engineer, SD V, WD XII, WRD, Quepem- Goa.

Letter no:- No. WRD/ WD XII/SD V/ F. 15/108/2021-22.

Dated:- 16-11-2021

Received on: 16-11-2021

Date of Testing: 18-11-2021

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F.15/1/2021	Coarse Sand	FM Silt & Clay Grading	3.044 3.80% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
F.15/2/2021	Aggregate-20 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	To get the 20mm graded aggregate nominal size blend 20mm & 10 mm metal in 1:1 proportion.
F.15/3/2021	Aggregate- 10 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	

Junior Engineer

Assistant Engineer

- Copy submitted to
- 1) Assistant Engineer, SD V, WD XII, WRD, Quepem- Goa.
 - 2) The Executive Engineer, Works Division XII, WRD, Gogol- Margao- Goa.
 - 3) Executive Engineer, WD XI, WRD, Rawanfond -Goa.
 - 4) Office File.