

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59/W.F. 59/2021 /200 / 2021-22 .

dated:05/01/2022

Name of the Work: Construction of nallah protection wall near the house of Yatish Suresh Naik in Village Panchayat Durbhat in Marcaim Constituency.

Sample Sent by: Assistant Engineer, SD IV, WD XI, WRD, Ponda-Goa

Letter No: No. WRD/WD XI/SD IV/ F.CF/425/2021-22.

Dated:- 3/1/2022

Received On: 03-01-2022

Date of Testing: 05-01-2022

REPORT

Sr No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F.59/01/2021	Coarse Sand	FM Silt & Clay Grading	2.368 2.00% Zone- II	2.3 to 3.1 Upto 5% I to III Zone	
F.59/02/2021	Aggregate-20 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	To get the 20mm graded aggregate nominal size blend
F.59/03/2021	Aggregate- 12.5 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	20mm & 12.5 mm metal in 1:1 proportion.

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD IV, WD XI, WRD, Ponda-Goa.
- 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
- 3) Office File.