

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59/W.F. 109/2021 / 562 / 2021-22 . dated: 19/03/2022

Name of the Work: Improvement of nallah from Holy cross Sulabhat in ward No. 8 to Caitani house at Arebhat in V.P. Agassaim in St. Andre Constituency.

Sample Sent by: Assistant Engineer , SD IV , WD I , WRD , Porvorim- Goa.

Letter No: MI/SD IV/WD I/WRD/F.38/2021-22/788.

Dated:- 17-03-2022.

Received on: 17-03-2022

Date of Testing: 19-03-2022

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F.109/01/2021	Coarse Sand	FM Silt & Clay Grading	2.946 2.00% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
F.109/02/2021	Aggregate-20 mm	Grading		As per IS-383:2016	To get the 20mm graded aggregate nominal size blend
F.109/03/2021	Aggregate- 12.5 mm	Grading		As per IS-383:2016	20mm & 12.5 mm metal in 1:1 proportion.

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD IV, WD I , WRD, Porvorim- Goa.
- 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
- 3) Executive Engineer, WD I, WRD, Porvorim-Goa.
- 4) Office File.