

**GOVERNMENT OF GOA**  
**WATER RESOURCES DEPARTMENT**  
**S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY**  
**Gogol - Margao - Goa.**

No. WRD / WD XI / SDIII / F.59/W.F. 110/2021 / 564 / 2021-22 . dated: 22/03/2022

Name of the Work: Improvement of nallah from Babu house to Prakash house at Mongada in V.P. Goa- Velha in St. Andre Constituency.

Sample Sent by: Assistant Engineer , SD IV , WD I , WRD , Porvorim- Goa.

Letter No: MI/SD IV/WD I/WRD/F.38/2021-22/796.

Dated:- 21-03-2022.

Received on: 21-03-2022

Date of Testing: 22-03-2022

**REPORT**

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F.110/01/2021	Coarse Sand	FM Silt & Clay Grading	2.710 3.10% Zone- II	2.3 to 3.1 Upto 5% I to III Zone	
F.110/02/2021	Aggregate-20 mm	Grading		As per IS-383:2016	To get the 20mm graded aggregate nominal size blend
F.110/03/2021	Aggregate- 12.5 mm	Grading		As per IS-383:2016	20mm & 12.5 mm metal in 1:1 proportion.

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD IV, WD I , WRD, Porvorim- Goa.
- 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
- 3) Executive Engineer, WD I, WRD, Porvorim-Goa.
- 4) Office File.