

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59/W.F. 31/2021 /164 / 2021-22 . dated: 10/12/2021

Name of the Work: Stabilization of hill slope and Improvement of waterways in Sy.No. 12& 39 in Village Dramapur of Salcete Taluka.

Sample Sent by: Assistant Engineer , SD I , WD II , WRD , Rawanfond- Goa.

Letter No: WRD / SD I/ WD II/ F.Estt/370/2021-22.

Dated:- 29-11-2021

Received on: 9/12/2021

Date of Testing: 10/12/2021

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F.31/01/2021	Coarse Sand	FM Silt & Clay Grading	2.710 3.10% Zone- II	2.3 to 3.1 Upto 5% I to III Zone	
F.31/02/2021	Aggregate-20 mm	Grading		As per IS-383:2016	To get the 20mm graded aggregate nominal size blend 20mm & 10 mm metal in 1:1 proportion.
F.31/03/2021	Aggregate- 10 mm	Grading		As per IS-383:2016	

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD I, WD II , WRD Rawanfond- Goa.
- 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
- 3) Executive Engineer, WD II, WRD, Rawanfond-Goa.
- 4) Rites.
- 5) Office File.