

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59 / WF.08-2020/ **170** / 2020-21.

dated: 30-11-2020

Name of the Work: Construction of protection wall of nallah from Satish Pednekar house to Hari Tuenkar house in Malbar Bund in V.P. Anjuna Caisua in Siolim Constituency.

Sample Sent by: Assistant Engineer, SD I, WD I, WRD, Porvorim-Goa

Letter No: No.WRD/M I/WD I/SD I/F.57/2020-21/459.

Dated:- 13-11-2020

Received on: 21-11-2020

Date of Testing: 23-11-2020

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
27/20	Coarse Sand	FM Silt & Clay Grading	2.564 1.80% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
28/20	Aggregate-12.5 mm	Grading		As per IS-383:2016	To get the 12.5 mm graded aggregate nominal size blend 12.5 mm & 10 mm metal in 1:1 proportion.
29/20	Aggregate- 10 mm	Grading		As per IS-383:2016	

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD I, WD I, WRD, Porvorim-Goa.
- 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
- 3) Executive Engineer, WD I, WRD, Porvorim- Goa.
- 4) Office File.