

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III. (C.P.O) QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD /SDIII / F.59 / 159 / 2019-20

dated: 06 -01-2019.

Name of the Work: Maintainance & Repair to the open Canal of Lift Irrigation Scheme at Zanodem in Sanguem Taluka for the year 2019-20.

Sample Sent by: Assistant Engineer, SD I, WD XII,WRD,Pajimol, Sanguem, Goa.

Letter No: WRD/SD I/ WD XII/F.47/387/2019-20

Dated:- 16/12/2019

Received on: 17-12-2019

Date of Testing: 20-12-2019

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
4733/19	Coarse Sand	FM Silt & Clay Grading	2.778 3.00% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
4734/19	Aggregate-20 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	To get the20mm graded aggregate nominal size blend
4735/19	Aggregate- 10 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	20mm & 10 mm metal in 1:1 proportion.

Dhananjay R. Nagvenkar
Technical Assistant

Pravin C Parsekar
Assistant Engineer

Copy submitted to 1) Assistant Engineer, SD I, WD XII , WRD, Pajimol, Sanguem-Goa.

2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.

3) Executive Engineer, WD XII, WRD, Pajimol, Sanguem-Goa.

4) Office File.