

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III. (C.P.O) QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / CPO / SDIII / F.59 /182/ 2019-20

dated: 13 -02-2020.

Name of the Work: Annual Maintainance & Urgent Repairs to the open Canal and distributaries of Govt L.I. Scheme at Potrem V.P Bhati in Sanguem Taluka for the year 2019-20.

Sample Sent by: Assistant Engineer, SD I, WD XII,WRD, Pajimol, Sanguem, Goa.

Letter No: WRD/SD I/ WD XII/F.47/413/2019-20

Dated:- 17/01/2020.

Received on: 30/01/2020

Date of Testing: 03/02/2020

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
4793/20	Coarse Sand	FM Silt & Clay Grading	2.665 3.20% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
4794/20	Aggregate-20 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	To get the 20mm graded aggregate nominal size blend
4795/19	Aggregate- 10 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	20mm & 10 mm metal in 1:1 proportion.

Dhananjay Nagvenkar
Technical Assistant

Pravin C Parsekar
Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SDI, WD XII,WRD, Pajimol, Sanguem, Goa.
- 2) The Executive Engineer, Works Division XII, WRD, Gogol, Margao - Goa.
- 3) Executive Engineer, WD XI, WRD, Rawanfond -Goa.
- 4) Office File.