

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59./ W.F. 23/2020/ 211 / 2020-21.

dated: 18-01-2021

Name of the Work: Construction of Protection wall for the nallah in Sy.No. 223 & 225 at Carvota, Loutolim in V.P. Loutolim in V.P. Nuvem Constituency.

Sample Sent by :- Assistant Engineer, SD I, WD II, WRD, Rawanfond- Goa.

letter no:- WRD/SD I/WD II/F.Esst/719/2020-21

Dated:- 22-12-2020

Received On: 15-01-2021

Date of Tesing: 18-01-2021

REPORT

Sr No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
109/2020	Coarse Sand	FM Silt & Clay Grading	2.606 1.40% Zone- II	2.3 to 3.1 Upto 5% I to III Zone	
110/2020	Aggregate-20 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	To get the 20mm graded aggregate nominal size blend 20mm & 10 mm metal in 1:1 proportion.
111/2020	Aggregate- 10 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD I, WD II, WRD, Rawanfond -Goa.
- 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
- 3) Executive Engineer, Work Division II, WRD, Rawanfond-Goa.
- 4) Office File.