

**GOVERNMENT OF GOA**  
**WATER RESOURCES DEPARTMENT**  
**S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY**  
**Gogol - Margao - Goa.**

No. WRD / WD XI / SDIII / F.59./ W.F. 41/2020-21/ **227** / 2020-21.

dated: 26-02-2021

Name of the Work: Protection to drain near Laxmikant Khedekar house ward No.3 V.P. priol of Priol Constituency of Ponda Taluka.

Sample Sent by :- Assistant Engineer, SD IV, WD XI, WRD, Ponda- Goa.

letter no:- WRD/ WD XI/ SD IV/F.cf/148/2020-21.

Dated:- 23-02-2021

Received On: 23-02-2021

Date of Testing: 26-02-2021

**REPORT**

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
203/2021	Coarse sand	FM Silt & Clay Grading	2.612 1.60% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
204/2021	Aggregate-20 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	To get the 20 mm graded aggregate of nominal size blend 20 mm & 12.5 mm metal in 1:1 proportion.
205/2021	Aggregate- 12.5 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD IV, WD XI, WRD, Ponda -Goa.
- 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
- 3) Office File.