

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59./ W.F. 40/2020-21/ **226** / 2020-21. dated: 25-02-2021.

Name of the Work: Construction of protection wall in Sy. No.12/0 ans 13/0 at Loyolawado, Utorda in Nuvem Constituency.

Sample Sent by :- Assistant Engineer, SD I, WD II , WRD, Rawanfond- Goa.

letter no:- WRD/ SD I / WD II/ F. Esst/848/2020-21.

Dated:- 22-02-2021

Received On: 22-02-2021

Date of Testing: 25-02-2021

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
199/2021	Coarse sand	FM Silt & Clay Grading	2.612 1.60% Zone II	2.3 to 3.1 Upto 5% I to III Zone	To get the 20mm graded aggregate nominal size blend 20mm & 10 mm metal in 1:1 proportion.
200/2021	Aggregate-20 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	
201/2021	Aggregate- 10 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD I, WD II , WRD, Rawanfond-Goa.
- 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
- 3) The Executive Engineer, Works Division II, WRD, Rawanfond- Goa.
- 4) Office File.