

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59 /176/ 2019-20.

dated: 11-02-2020

Name of the Work: Stabilization of nallah bank in Plot No 12 under Survey No. 290/1 at Naikabhat in Sao Jose De Areal village Panchayat in Velim Constituency.

Sample Sent by :- Assistant Engineer, SD I, WD II , WRD, Rawanfond- Goa.

letter no:- WRD/ SD I/WD II/ F.Esst/421/2019-20

Date:- 19-01-2018

Received On: 03/02/2020

Date of Tesing:

06/02/2020.

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
4803/20	Coarse Sand	FM Silt & Clay Grading	2.654 3.00% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
4804/20	Aggregate-40mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	
4805/20	Aggregate-20 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	To get the 40mm graded aggregate nominal size blend 40mm,20mm & 10 mm metal in 1:1:1 proportion.
4806/20	Aggregate- 10 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	

Dhananjay Nagvenkar
Technical Assistant

Pravin C Parsekar
Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SDI, WD II,WRD, Rawnafond, Goa.
- 2) The Executive Engineer, Works Division II, WRD, Rawanfond, Goa.
- 3) Executive Engineer, WD XI, WRD, Rawanfond -Goa.
- 4) Office File.