

GOVERNMENT OF GOA
QUALITY CONTROL LABORATORY
WATER RESOURCES DEPARTMENT

Test Report No.: WRD / QC / F.6-2 / Cube -T : 8809 / Lab / **440** / 2019 - 20 Dated:- 15 / 02 / 2020

Laboratory : Bicholim - Goa.
Sub Division V (QC)/WRD/ Bicholim- Goa.

Name of work :- Maintenance and Repairs to the Field Channel 1 and 2 under Direct Outlet 7 L of R.B.M.C. of T.I.P. at Village Hassapur in Pernem Taluka.

Ref to requisition No.:- WRD / SD I / WDVII / F.211-10 /2019-20/ **345** Dated :- 14 / 02 / 2020.

Qty. Recived. : 01 Sets of cube Date of Receipt:- 14 / 02 / 20200. Tested on: - 14 / 02 / 2020 Ref to CPWD :2009, Vol. I

Sample: Cube Mix 1 : 2 : 4 O.S No. : 3235 /SS. Lab. Sample No.: 7926 Tested By: Mrs. S.B.Naik Shirodkar. J.E.

SR. NO.	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min.Value permissable	% above or below	REMARK
1	Plain Cement Concrete cube of mix 1 : 2 : 4 , cast on 17 / 01 / 2020. PCC for FC Piers and Chambers.	28 th day compressive strength	215.20	Kg/Cm ²	210.00 Kg/cm ²	4.27	1) Qty represents - 24.00 Cum.
233.32			Kg/Cm ²				
208.40			Kg/Cm ²				
Average		218.98	Kg/Cm²				

Copy to: 1. The Assistant Engineer , Sub Division -I , W.D. VII, WRD, Dhargal - Pernem - Goa.

2. Copy submitted to The Superintending Engineer ,CPO,WRD, Sinchai Bhavan, Porvorim Goa for kind Information.

3. Copy submitted to The Executive Engineer ,Works Division - VII ,WRD, Dhargal - Pernem - Goa.

4. QC Lab File. 5. Bill File.

Junior Engineer

Assistant Engineer