

GOVERNMENT OF GOA
QUALITY CONTROL LABORATORY
WATER RESOURCES DEPARTMENT

Test Report No.: WRD / QC / F.6-2 / Cube -T : 4524/ Lab /82/ 2022 - 23 Dated:- 18/ 05/2022.

Laboratory : Bicholim - Goa.
Sub Division V (QC)/WRD/Goa.

Name of work : Construction of Bandhara (Rajwalacho bandh) at Village Golauli in V.P. Dongurli Thane in Sattari Taluka.

Ref. to Requisition No.: MI/WDVI/WRD/SDII/f-24/22-23/20 Dt.:- 21/ 04/ 2022

Qty. Recived. : 01 Set of cube Date of Receipt:- 21/04/ 2022. Tested on: - 12/05/2022 as per due dates. Ref to CPWD :2009, Vol. I

Sample:Cube Mix PCC **1:2:4** O.SNo.:0795/R.K Lab. Sample No.: 3965 Tested By: Mrs. R. R. Kadam A.E.

REPORT PAGE 01 OF 01

SR.N O.	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min.Valu e permissable	% above or below	REMARK
1	Cement concrete cube of mix 1 : 2: 4 , cast on 14/04/2022. PCC for D/s Toe wall.	28 th day compressive strength	226.53 262.77 244.65	Kg/Cm ² Kg/Cm ² Kg/Cm ²	210.00 Kg/cm ²	16.50	Qty represents - 10.00 m3.
		Average	244.65	Kg/Cm²			

Copy to: 1. The Assistant Engineer , SD II , WDVI , WRD,Valpoi-Sattari - Goa.

2. Copy submitted to The Superintending Engineer ,CPO,WRD, Sinchai Bhavan, Porvorim Goa for kind Information.

3. Copy submitted to The Executive Engineer, WD VI, WRD, Bicholim - Goa.

4. QC Lab File. 5. Bill File.

Assistant Engineer