

GOVERNMENT OF GOA
QUALITY CONTROL LABORATORY
WATER RESOURCES DEPARTMENT

Test Report No.: WRD / QC / F.6-2 / Cube -T : 7167 / Lab / **188** / 2019 - 20 Dated:- 14/ 06 / 2019 Laboratory : Bicholim - Goa.
Sub Division V (QC)/WRD/ Bicholim- Goa.

Name of work : Construction of Anjuna Distributory taking off at ch. 28.97 km of the Left bank main canal of Tillari Irrigation Project in Siolim & Anjuna Village of Bardez Taluka. Part III : Construction of Rising main from ch.4.50km to ch. 7.29kms, Break Pressure tank (BPT), Gravity main from ch.0.00km to ch. 1.00 kms and reinstatement of allied structures for Anjuna Distributory in Siolim and Assagao Village of Bardez Taluka.

Ref. to Requisition No.: WRD /WD VIII / SD III / W F.32 /(PART -III)/2019-20/43 dated :-17 / 05 / 2019.

Qty. Recived. : 01 Set of cube Date of Receipt:- 17/ 05 / 2019. Tested on: - 11 /06/2019 Ref to CPWD :2002, Vol. I

Sample: Cube Mix 1 : 1.5 : 3 O.S No. : 2216/SS. Lab. Sample No.: 4730 Tested By: Mrs. S.B. Naik Shirodkar. J.E.

REPORT PAGE 01 OF 01

SR. NO.	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min.Value permissable	% above or below	REMARK
1	Cement concrete cube of mix 1 : 1.5 : 3 , cast on 14/05/2019, for Anchor block. (S1)	28 th day	289.95	Kg/Cm ²	265.00 Kg/cm ²	19.67	Qty represents - 5.00 Cum.
		compressive strength	323.93	Kg/Cm ²			
			337.52	Kg/Cm ²			
		Average	317.14	Kg/Cm²			

Copy to: 1. The Assistant Engineer , SDIII , WD VIII, WRD, Karaswada, Bardez - Goa.

2. Copy submitted to The Superintending Engineer ,CPO,WRD, Sinchai Bhavan, Porvorim Goa for kind Information.

3. Copy submitted to The Executive Engineer ,WD VIII ,WRD, Karaswada -Bardez - Goa.

4. QC Lab File. 5. Bill File.

Junior Engineer

Assistant Engineer