

GOVERNMENT OF GOA
QUALITY CONTROL LABORATORY
WATER RESOURCES DEPARTMENT

Test Report No.: WRD / QC / F.6-2 / Cube -T :2867/ Lab / 243 / 2021 - 22 Dated:- 03/01/2022.

Laboratory : Bicholim - Goa.

Sub Division V (QC)/WRD/ Bicholim- Goa.

Name of work :Construction of Slab Culvert for Brahmani Maya Mandir at Ch.2.800 Km of RBMC of AIP at Shirolu Keri in Sattari Taluka.

Ref. to Requisition No.: F.37/SDI/WDV/AIP/WRD/2021-22/100/133 Dated :- 29/ 11/ 2021.

Qty. Received. :01 Set of cube Date of Receipt:- 29/11/ 2021. Tested on: -21/12/2021 as per due dates. Ref to CPWD :2009, Vol. I

Sample: Cube Mix 1:1.5:3 O.S No. : 7216/ SS . Lab. Sample No.: 2433 Tested By: Mrs. Shirodkar. J.E.

REPORT PAGE 01 OF 01

SR. NO.	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min. Value permissable	% above or below	REMARK
1	Cement concrete cube of mix 1:1.5:3 , cast on 23/11/2021.R.C.C for bridge of Slab Culvert.	28 th day compressive strength	280.89	Kg/Cm ²	265.00 Kg/cm ²	5.71	Qty represents -7.00 Cum.
			269.57	Kg/Cm ²			
			289.95	Kg/Cm ²			
		Average	280.14	Kg/Cm²			

Copy to: 1. The Assistant Engineer , SDI , WDV,WRD, Kerim, Sattari - Goa.

2. Copy submitted to The Superintending Engineer ,CPO,WRD, Sinchai Bhavan, Porvorim Goa for kind Information.

3. Copy submitted to The Executive Engineer , WDV,WRD, Karapur tisk - Sanqulim - Goa..

4. QC Lab File. 5. Bill File.

Junior Engineer

Assistant Engineer