

GOVERNMENT OF GOA
QUALITY CONTROL LABORATORY
WATER RESOURCES DEPARTMENT

Test Report No.: WRD / QC / F.6-2 / Cube -T :2208/ Lab / **106** / 2021 - 22 Dated:- 14/ 06 / 2021. Laboratory : Bicholim - Goa
Sub Division V (QC)/WRD/ Bicholim- Goa.

Name of work :Improvement to Bastora Minor-2 Branch 3 and Bastora Minor 3/OL-2 of Calangute Distributory LBMC in Guirim and Sangolda villlage of Bardez Taluka.

Ref. to Requisition No.: SDI/WDVIII/WRD/WF.66/21-22/28 Dated :- 24/ 05 / 2021.

Qty. Recived. :01 Sets of cube Date of Receipt:- 25/ 05 / 2021. Tested on: 10/06/2021 as per due dates. Ref to CPWD :2009, Vol. I

Sample: Cube Mix 1:2:4 O.S No.6439/SS Lab. Sample No.: 1605 Tested By: Mrs. Shirodkar. J.E.

REPORT PAGE 01 OF 01

SR. NO	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min.Value permissable	% above or below	REMARK
1	Cement concrete cube of mix 1 :2 : 4 , cast on 13/05/2021. For Beds of Chamber.	28 th day compressive strength	217.47	Kg/Cm ²	210.00 Kg/cm ²	8.23	Qty represents -13.00 Cum.
			237.85	Kg/Cm ²			
			226.53	Kg/Cm ²			
		Average	227.28	Kg/Cm²			

Copy to: 1. The Assistant Engineer , SD I , WD VIII, WRD,Karaswada-Bardez- Goa.

2. Copy submitted to The Superintending Engineer ,CPO,WRD, Sinchai Bhavan, Porvorim Goa for kind Information.

3. Copy submitted to The Executive Engineer , WD VIII ,WRD, Karaswada-Bardez-Goa.

4. QC Lab File. 5. Bill File.

Junior Engineer

Assistant Engineer