

GOVERNMENT OF GOA
QUALITY CONTROL LABORATORY
WATER RESOURCES DEPARTMENT

Test Report No.: WRD / QC / F.6-2 / Cube -T : 2328/ Lab / 120 / 2021 - 22 Dated:-24/06/ 2021. Laboratory : Bicholim - Goa.

Sub Division V (QC)/WRD/ Bicholim- Goa.

Name of work : Improvement to Bastora Minor 2 Branch 3 and Bastora Minor 3/OL2 of Calangute Distributory of LBMC in Guirim and Sangolda village of Bardez Taluka.

Ref. to Requisition No.: SDI/WDVIII/WRD/WF-66/2021-22/30 Dated :- 28/ 05/ 2021.

Qty. Recived. :01 Sets of cube Date of Receipt:- 28/05/ 2021. Tested on: -21/06/2021 as per due dates. Ref to CPWD :2009, Vol. I

Sample: Cube Mix 1:2:4 O.S No. : 6561/ SS . Lab. Sample No.: 1629 Tested By: Mrs. Shirodkar. J.E.

REPORT PAGE 01 OF 01

SR. NO.	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min.Value permissable	% above or below	REMARK
1	Cement concrete cube of mix 1:2:4 , cast on 24/05/2021.P.C.C for Beds & Chamber.	28 th day compressive strength	212.93	Kg/Cm ²	210.00 Kg/cm ²	8.23	Qty represents -13.00 Cum.
			237.85	Kg/Cm ²			
			231.06	Kg/Cm ²			
		Average	227.28	Kg/Cm²			

Copy to: 1. The Assistant Engineer , SD I , WD VIII,WRD, Karaswada-Bardez - Goa.

2. Copy submitted to The Superintending Engineer ,CPO,WRD, Sinchai Bhavan, Porvorim Goa for kind Information.

3. Copy submitted to The Executive Engineer , WD VIII,WRD, Karaswada-Bardez - Goa.

4. QC Lab File. 5. Bill File.

Junior Engineer

Assistant Engineer