

GOVERNMENT OF GOA
QUALITY CONTROL LABORATORY
WATER RESOURCES DEPARTMENT

Test Report No.: WRD / QC / F.6-2 / Cube -T : 1268,1294 / Lab / **294** / 2020 - 21 Dated:- 15 / 03 / 2021. Laboratory : Bicholim - Goa.
Sub Division V (OC)/WRD/ Bicholim- Goa.

Name of work : Construction of Kamurlim branch from ch.4.61km to ch.5.320km and OL-5 and OT and its field network of LBMC of TIP at village Kamurlim in Bardez Taluka.

Ref. to Requisition No.: SDI/WDVIII/WRD/WF-34/2020-21/204 Dated :- 15/ 02/ 2021.

Qty. Recived. :02 Sets of cube Date of Receipt:- 15/02/ 2021. Tested on: -09/03/2021 & 12/03/2021 as per due dates. Ref to CPWD :2009, Vol. I

Sample: Cube Mix 1:2:4 O.S No. :5360,5394/SS Lab. Sample No.: 478 & 479 Tested By: Mrs. S.B. Naik Shirodkar. J.E.

REPORT PAGE 01 OF 01

SR. NO.	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min.Value permissable	% above or below	REMARK
1	Cement concrete cube of mix 1 :2 : 4 , cast on 09/02/2021. P.C.C. for Beds and Chamber.	28 th day compressive strength	212.93	Kg/Cm ²	210.00 Kg/cm ²	10.03	Qty represents -6.00 Cum.
			235.59	Kg/Cm ²			
			244.65	Kg/Cm ²			
		Average	231.06	Kg/Cm²			
2	Cement concrete cube of mix 1 :2 : 4 , cast on 12/02/2021. P.C.C. for Wall chamber & Beds of Chamber.	28 th day compressive strength	244.65	Kg/Cm ²	210.00 Kg/cm ²	16.86	Qty represents -9.00 Cum.
			231.06	Kg/Cm ²			
			260.51	Kg/Cm ²			
		Average	245.40	Kg/Cm²			

Copy to: 1. The Assistant Engineer , SD I , WD VIII, WRD-Karaswada-Bardez - Goa.

2. Copy submitted to The Superintending Engineer ,CPO,WRD, Sinchai Bhavan, Porvorim Goa for kind Information.

3. Copy submitted to The Executive Engineer , WD VIII ,WRD, Karaswada-Bardez - Goa.

4. QC Lab File. 5. Bill File.

Junior Engineer

Assistant Engineer