

GOVERNMENT OF GOA
QUALITY CONTROL LABORATORY
WATER RESOURCES DEPARTMENT

Test Report No.: WRD / QC / F.6-2 / Cube -T : 4206/ Lab / 62/ 2022 - 23 Dated:- 04/05/2022.

Laboratory : Bicholim - Goa.
Sub Division V (QC)/WRD/ Bicholim- Goa.

Name of work : Improvement to Kodo Katar bund along the bank of Chapora river at Camurlim in Tivim Constituency.

Ref. to Requisition No.: S.D.II/W.D.I/WRD/F.24/22-23/54 Dt.:-02/ 05/ 2022

Qty. Recived. : 01 Set of cube Date of Receipt:- 02/ 05 / 2022. Tested on: 02/05/2022 as per due dates. Ref to CPWD :2009, Vol. I

Sample: Cube Mix **1:2:4** O.S No. :8462/SS Lab. Sample No.: 4191 Tested By: Mrs. S. B. Naik Shirodkar J.E.

REPORT PAGE 01 OF 01

SR. NO	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min.Value permissable	% above or below	REMARK
1	Cement concrete cube of mix 1:2:4 , cast on 04/04/2022. For Bed Block - Ch 479m to 489m.	28 th day compressive strength	224.26	Kg/Cm ²	210.00 Kg/cm ²	6.07	Qty represents - 5.50 m3.
			217.47	Kg/Cm ²			
			226.53	Kg/Cm ²			
		Average	222.75	Kg/Cm²			

Copy to: 1. The Assistant Engineer , SD II , WDI, WRD, Mapusa, Bardez - Goa.

2. Copy submitted to The Superintending Engineer ,CPO,WRD, Sinchai Bhavan, Porvorim Goa for kind Information.

3. Copy submitted to The Executive Engineer , WDI ,WRD, Porvorim - Goa.

4. QC Lab File. 5. Bill File.

Assistant Engineer