

GOVERNMENT OF GOA
QUALITY CONTROL LABORATORY
WATER RESOURCES DEPARTMENT

Test Report No.: WRD / QC / F.6-2 / Cube -T :- 5466/ Lab / **191**/ 2022 - 23 Dated:- 14/11/2022.

Laboratory : Bicholim - Goa.
Sub Division V (QC)/WRD/ Bicholim- Goa.

Name of work : - Roof top rain water harvesting in Irrigation complex of Division V at Karapur, Sankhali Goa.

Ref. to Requisition No: F.W.01/WRD/SDII/WDV/AIP/186/ 2022-23 dated :- 07/11/2022.

Qty. Recived. : 01 Set of cube Date of Receipt:- 08/11/2022 Tested on: - 12/11/2022 Ref to CPWD :2009, Vol. I

Sample: Cube Mix 1:1:1.5:3 O.S No: 9471/SS. Lab. Sample No: 5372. Tested By: Mrs. S.B. Naik Shirodkar J.E.

REPORT PAGE 01 OF 01

SR.N O.	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min.Value permissible	% above or below	REMARK
1	Cement concrete cube of mix 1:1:1.5:3 , cast on 05/11/2022. RCC For Slab of Sump tank.	7 th day compressive strength	190.28	Kg/Cm ²	175.00 Kg/cm ²	13.91	1.Qty represent -9.07 cum. 2. 28th day test due on 03/12/2022.
			212.93	Kg/Cm ²			
			194.81	Kg/Cm ²			
		Average	199.34	Kg/Cm²			

Copy to: 1. The Assistant Engineer SD II, WD V,WRD, Karapur Tisk, Sankhali Goa.

2. Copy Submitted to The Superintending Engineer, CPO, WRD,Sinchai Bhavan Porvorim-Goa for kind Information.

3. Copy Submitted to The Executive Engineer, W.D.VI, WRD Sankhali-Goa.

4. QC Lab File. 5. Bill File.

Junior Engineer

Assistant Engineer