

GOVERNMENT OF GOA
QUALITY CONTROL LABORATORY
WATER RESOURCES DEPARTMENT

Test Report No.: WRD / QC / F.6-2 / Cube -T : 2228 / Lab / **107** / 2021 - 22 Dated:- 14/06 /2021. Laboratory : Bicholim - Goa.
Sub Division V (QC)/WRD/ Bicholim- Goa.

Name of work :Desilting of Rivulets /Poi, Agriculture fields and reconstruction of existing sluice in Savat Khazan and kharat khazan field at Shirgao in Bicholim Taluka. .

Sub Est.IV:-Reconstruction of sluice (Near Mharingan Temple) in Kharat Khazan at Shirigao village in Bicholim Taluka.

Ref. to Requisition No.: F.36/SDIII/WDVI/WRD/2021-22/35 Dated :- 21/ 05/ 2021.

Qty. Received. :01 Sets of cube Date of Receipt:- 22/05/ 2021. Tested on: -12/06/2021 as per due dates. Ref to CPWD :2009, Vol. I

Sample: Cube Mix PCC 1:2:4 O.S No. : 6459/SS Lab. Sample No.: 1600 Tested By: Mrs. Shirodkar. J.E.

REPORT PAGE 01 OF 01

SR. NO.	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min.Value permissable	% above or below	REMARK
1	Cement concrete cube of mix 1:2:4 , cast on 15/05/2021. P.C.C. for RHS Abutment Foundation of retaining wall.	28 th day compressive strength	235.59	Kg/Cm ²	210.00 Kg/cm ²	3.91	Qty represents -6.00 Cum.
			215.20	Kg/Cm ²			
			203.87	Kg/Cm ²			
		Average	218.22	Kg/Cm²			

Copy to: 1. The Assistant Engineer , SD III , WD VI, WRD,Mulgao - Goa.

2. Copy submitted to The Superintending Engineer ,CPO,WRD, Sinchai Bhavan, Porvorim Goa for kind Information.

3. Copy submitted to The Executive Engineer , WD VI ,WRD, Bicholim - Goa.

4. QC Lab File. 5. Bill File.

Junior Engineer

Assistant Engineer