

GOVERNMENT OF GOA
QUALITY CONTROL LABORATORY
WATER RESOURCES DEPARTMENT

Test Report No.: WRD / QC / F.6-2 / Cube -T : 1963 / Lab / **71** / 2021 - 22 Dated:- 15/05 / 2021. Laboratory : Bicholim - Goa.
Sub Division V (QC)/WRD/ Bicholim- Goa.

Name of work :Desilting of Rivulets /Poi, Agriculture fields and reconstruction of existing sluice in Savat Khazan and kharat khazan field at Shirgao in Bicholim Taluka.

Sub Est.III:-Reconstruction of sluice (Navi Manas) in Kharat Khazan at Shirgao village in Bicholim Taluka.

Ref. to Requisition No.: F.36/SDIII/WDVI/WRD/2021-22/16 Dated :- 23/04/ 2021.

Qty. Received. :01 Sets of cube Date of Receipt:- 23/04/ 2021. Tested on: -14/05/2021 as per due dates. Ref to CPWD :2009, Vol. I

Sample: Cube Mix 1:1.5: 3 O.S No. : 6188/SS Lab. Sample No.: 1321 Tested By: Mrs. Shirodkar. J.E.

REPORT PAGE 01 OF 01

SR. NO.	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min.Value permissable	% above or below	REMARK
1	Cement concrete cube of mix 1 :1.5 : 3 , cast on 16/04/2021. R.C.C. For Bridge over sluice gate.	28 th day compressive strength	299.01	Kg/Cm ²	265.00 Kg/cm ²	15.69	Qty represents -7.00 Cum.
303.55		Kg/Cm ²					
317.14		Kg/Cm ²					
Average		306.57	Kg/Cm²				

Copy to: 1. The Assistant Engineer , SD III , WD VI, WRD,Mulgao - Goa.

2. Copy submitted to The Superintending Engineer ,CPO,WRD, Sinchai Bhavan, Porvorim Goa for kind Information.

3. Copy submitted to The Executive Engineer , WD VI ,WRD, Bicholim - Goa.

4. QC Lab File. 5. Bill File.

Junior Engineer

Assistant Engineer