

GOVERNMENT OF GOA
QUALITY CONTROL LABORATORY
WATER RESOURCES DEPARTMENT

Test Report No.: WRD / QC / F.6-2 / Cube -T : 2872/ Lab / 244 / 2021 - 22 Dated:- 05 / 01 / 2022.

Laboratory : Bicholim - Goa.
Sub Division V (QC)/WRD/ Bicholim- Goa.

Name of work :Improvement to CADA building in Tillari Irrigation Project Complex at Karaswada Bardez-Goa.

Ref. to Requisition No.: SDIII/WDVIII/WRD/W.F.89/2021-22/242 Dated :- 22/ 12/ 2021.

Qty. Received. :01 Set of cube Date of Receipt:- 22/12/ 2021. Tested on: -22/12/2021 as per due dates. Ref to CPWD :2009, Vol. I

Sample: Cube Mix 1:2:4 O.S No. : 7221/SS. Lab. Sample No.: 2516 Tested By: Mrs. S.B. Naik Shirodkar J.E.

REPORT PAGE 01 OF 01

SR. NO.	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min.Value permissable	% above or below	REMARK
1	Cement concrete cube of mix 1 : 2 : 4 , cast on 24/11/2021 for Bed PCC	28th day	219.73	Kg/Cm ²	210.00 Kg/cm ²	10.75	Qty. represents -26.00 Cum
		compressive	237.85	Kg/Cm ²			
		strength	240.12	Kg/Cm ²			
		Average	232.57	Kg/Cm²			

Copy to: 1. The Assistant Engineer , SD III , WD VIII, Karaswada-Bardez - Goa.

2. Copy submitted to The Superintending Engineer ,CPO,WRD, Sinchai Bhavan, Porvorim Goa for kind Information.

3. Copy submitted to The Executive Engineer , WD VIII, WRD, Karaswada-Bardez - Goa.

4. QC Lab File. 5. Bill File.

Junior Engineer

Assistant Engineer