

GOVERNMENT OF GOA
QUALITY CONTROL LABORATORY
WATER RESOURCES DEPARTMENT

Test Report No: WRD/QC/F.6-2/Cube -T : 6346/Lab/**307**/2022 - 23 Dated:- 13/03/2023.

Laboratory : Bicholim - Goa.
Sub Division V (QC)/WRD/ Bicholim- Goa.

Name of work : Construction of Raw Water Pumping Station at Amthane for Dhumacem water treatment Plant and Industrial Estate at Latambarcem.

Ref. to Requisition No : WRD/WDVI/SDI/F.W.247/2022-23/447. Dated :- 08/03/2023.

Qty. Recived : 01 Set of cube Date of Receipt:- 08/03/2023 Tested on: - 09/03/2023 . Ref to CPWD :2009, Vol. I

Sample: Cube Mix **1:1.5:3** O.S No : 373/SS. Lab. Sample No: 6413. Tested By: Mrs. S.B. Naik Shirodkar. J.E.

REPORT PAGE 01 OF 01

SR.N O.	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min.Value permissable	% above or below	REMARK
1	Cement concrete cube of mix 1:1.5:3 , cast on 02/03/2023. RCC for Footings of Pump House.	7 th day compressive strength	163.10	Kg/Cm ²	175.00 Kg/cm ²	7.01	1.Qty represent -11.00 cum. 2. 28th day test due on 30/03/2023.
			190.28	Kg/Cm ²			
			208.40	Kg/Cm ²			
		Average	187.26	Kg/Cm²			

Copy to: 1. The Assistant Engineer , SD I, WD VI, WRD, Bicholim - Goa.

2. Copy submitted to The Superintending Engineer ,CPO,WRD, Sinchai Bhavan, Porvorim Goa for kind Information.

3. Copy submitted to The Executive Engineer, WD VI, WRD, Bicholim - Goa.

4. QC Lab File. 5. Bill File.

Junior Engineer

Assistant Engineer